
Main Board



POLARITY WARNING! Double check Polarity on Drum connection as the wire color is not depicted accurately of VCC and Ground (In picture the red wire is on ground(-) and the black wire is VCC(+))

Probe is NTC150K as per OEM. Someone reported that this probe ATSC230K-100 should work following same profile as the probe used in Skywalker.

Revision #4
Created 2024-04-07 02:49:49 UTC by Nirecue
Updated 2024-04-07 03:02:36 UTC by Nirecue